

Policyholder

Name	Phone Number	Address
Mrs. Jane Jones	(705) 313-4436	74 Strongberg Drive, Winnipeg, MB, Canada

Claim Details

Carrier Identifier	Contractor Identifier	Assignment Identifier
CL89964-9	001-102121	--
Project Manager	Date of Loss	Date Claim Created
--	Oct 21, 2021	Oct 27, 2021
Insurance Company	Adjuster	Policy Number
Allstate	--	1136JH97
Source of Loss	Initial Category of Water	
Broken supply line	Category 1	

Dehumidifier Calculator

Atmosphere	Class of Water	Atmosphere Volume	Recommended AHAM Pints/Day
Main Floor	Class 2	3856 ft ³	145 pints/day

Dehumidifiers

Atmosphere	Name	Placed	Removed	Energy usage	Days on site
Kitchen	XPower XD-85L (DH-001)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	38.91 kWh	3 days
Kitchen	XPower XD-85L (DH-001)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	38.91 kWh	3 days
Dining Room	Drieaz Evolution (DH-015)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	29.04 kWh	3 days
Dehumidifier Total				106.86 kWh	9 days

Air Mover Calculator

Area	Floor	Ceiling	Walls	Insets or Offsets	Recommended
Kitchen	0 ft ²	0 ft ²	0 ft ²	2	6 air movers
Dining Room	80 ft ²	0 ft ²	0 ft ²	0	4 air movers

Air Movers

Area	Name	Placed	Removed	Energy usage	Days on site
Kitchen	Xpower X400 (AM-008)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Kitchen	Xpower X400 (AM-009)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Kitchen	Xpower X400 (AM-002)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Kitchen	Xpower X400 (AM-001)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Dining Room	Xpower X400 (AM-015)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Kitchen	Drieaz Velo Low Profile (AM-026)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	11.03 kWh	3 days
Dining Room	Xpower X400 (AM-010)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Dining Room	Xpower X400 (AM-011)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	17.42 kWh	3 days
Kitchen	Drieaz Sahara Pro (AM-021)	Nov 2, 3:00 PM	Nov 4, 5:30 PM	27.30 kWh	3 days
Air Mover Total				160.29 kWh	27 days

Air Scrubbers

Atmosphere	Name	Placed	Removed	Energy usage	Days on site
Air Scrubber Total				0 kWh	0 days